

STATEMENT OF CORRECTIVE ACTION

The following actions were taken to correct each of the deficiencies noted during the vessel sanitation inspection conducted on board Radisson Seven Seas Cruises' vessel *ssc Radisson Diamond* on March 14, 2002 at the Port of San Juan, Puerto Rico.

No.	Ref.	Pts.	Critical.	Description.	Corrective Actions.
1	21	1	No	Food Service General The interior spaces of the grills were not easily cleanable.	All grills will be rebuilt by a stainless steel company in the near future to allow easy cleaning of all interior spaces.
2	27*	0	No	Galley - Deck 9 The interior of the grill was soiled with food and grease residue.	A cleaning schedule has been implemented. The cleanliness of the grills is now being checked during the regular shipboard maintenance and health inspections
3	21	1	No	Galley - Deck 6 The door closures for the cleaning locker were broken.	The door closures have been repaired.
4	21	1	No	Food Service - General Non-food contact surfaces of some equipment contained gaps, holes and other non-easily cleanable features.	All stainless steel work is to be carried out in the near future and should be completed within the next two months.
5	33	1	No	Food Service - General Decks and bulkheads in various areas contained some cracked deck tiles, recessed grouting, open seams, and other non-easily cleanable features	The replacement and rerouting of the deck tiles is in progress. Stainless steel work will be carried out in the near future. Open seams have been re-caulked with sealant approved for use in food service areas.
6	*	0	No	Potable Water It is recommended that a pH adjustment system shall be provided for the potable water system.	A pH adjustment system has been put in place for portable water that is produced on board.

Othmar Hehli
Senior Director of Operations
April 8, 2002
Radisson Seven Seas Cruises